

修復前後照片

一、動力室

	
動力室外立面施工前	施工後
	
動力室一樓內部施工前	施工後
	
動力室二樓施工前	施工後

二、煤料庫

	
<p>煤料庫施工前</p>	<p>施工後</p>
	
<p>煤料庫施工前</p>	<p>施工後</p>
	
<p>煤料庫施工前照</p>	<p>施工後</p>

三、乾燥室

 A photograph showing the exterior of a building before renovation. The facade is weathered and grey, with a large window and a wooden door. A blue tarp is draped over the side.	 A photograph showing the exterior of the same building after renovation. The facade is now painted a light blue, and the door is a darker blue. The area is cleaner and more finished.
<p>乾燥室正面施工前</p>	<p>施工後</p>
 A photograph showing the interior of the drying room before renovation. The floor is made of old, uneven wooden planks, and the walls are dark and cluttered with debris.	 A photograph showing the interior of the drying room after renovation. The floor is now a smooth, light-colored concrete surface. A metal frame structure is visible, and the walls are white.
<p>乾燥室內部施工前</p>	<p>施工後</p>
 A photograph showing the rear of the building before renovation. The concrete walls are weathered and stained. There is a small porch area with steps leading to a door.	 A photograph showing the rear of the building after renovation. The concrete walls are now painted a light blue. A blue corrugated metal door is visible, and the porch area is finished.
<p>乾燥室背面施工前</p>	<p>施工後</p>

四、手編工廠

	
手編工廠施工前南向入口	施工後
	
手編工廠施工前內部	施工後
	
手編工廠施工前東向立面	施工後

五、辦公室

	
<p>辦公室施工前西向外觀</p>	<p>施工後</p>
	
<p>辦公室施工前東側內部空間</p>	<p>施工後</p>
	
<p>辦公室施工前北向外廊</p>	<p>施工後</p>

六、加工廠

	
加工廠施工前南向外觀	施工後
	
加工廠施工前內部	施工後
	
加工廠施工前內部記錄照	施工後
	
加工廠施工前北向	施工後