

112第1季嘉義市水質監測結果

測站名稱	採樣日期	河川污染指數	水溫	酸鹼值	導電度	溶氧(電極法)	生化需氧量	化學需氧量	懸浮固體	大腸桿菌群	氨氮	鎘	鉛	銅	鋅	錳	鉻	備註
廬山橋	112/1/10	-	22.6	7.8	-	-	9.0	17.6	11.5	25,000	2.32	ND (<0.0005)	ND (<0.0030)	0.005	0.039	0.178	0.001	
台林橋																		水深不足，無採樣
華興橋	112/1/10	-	29.2	7.7	-	-	10.5	37.2	11.3	220,000	5.74	ND (<0.0005)	ND (<0.0030)	0.003	0.087	0.320	0.002	
忠義橋	112/1/10	-	23.5	8.2	-	-	3.5	8.4	6.8	2,800	0.20	ND (<0.0005)	ND (<0.0030)	0.001	0.012	0.096	0.002	
永欽一號橋	112/1/10	-	23.7	7.5	-	-	4.9	9.1	6.7	74,000	4.57	ND (<0.0005)	ND (<0.0030)	ND (<0.0012)	ND (<0.0082)	0.378	0.001	
蘭潭進水口	112/1/10	-	21.4	8.5	-	-	1.9	7.0	60.3	390	0.11	ND (<0.0005)	0.004	ND (<0.0012)	ND (<0.0082)	0.060	0.002	
蘭潭取水口	112/1/10	-	21.8	8.7	-	-	1.7	7.7	4.4	340	0.11	ND (<0.0005)	ND (<0.0030)	ND (<0.0012)	ND (<0.0082)	0.011	ND (<0.0008)	
香湖公園																		水深不足，無採樣
頂庄社區(入)	112/1/11	-	21.0	7.7	-	-	9.9	53.4	5.6	-	7.52	ND (<0.0005)	ND (<0.0030)	ND (<0.0012)	ND (<0.0082)	0.106	0.001	
頂庄社區(出)	112/1/11	-	22.5	7.8	-	-	9.0	15.4	4.3	-	5.95	ND (<0.0005)	0.005	0.003	0.020	0.143	ND (<0.0008)	
十四甲排水	112/1/11	-	22.4	8.3	-	-	29.6	121	25.3	-	19.1	ND (<0.0005)	ND (<0.0030)	0.005	0.025	0.226	ND (<0.0008)	
民雄排水	112/1/11	-	26.2	7.6	-	-	8.6	43.9	10.7	-	1.27	0.001	0.014	0.015	0.941	0.136	0.010	
北區排水	112/1/11	-	22.3	7.6	-	-	20.0	103	5.2	-	11.5	ND (<0.0005)	ND (<0.0030)	ND (<0.0012)	0.013	0.215	ND (<0.0008)	
西區排水	112/1/11	-	22.2	7.8	-	-	33.2	54.4	6.3	-	26.4	ND (<0.0005)	ND (<0.0030)	0.003	0.012	0.134	ND (<0.0008)	
中央排水	112/1/11	-	22.2	8.2	-	-	35.9	74.8	8.0	-	8.52	ND (<0.0005)	ND (<0.0030)	0.004	0.011	0.161	0.001	
南排排水	112/1/11	-	23.2	7.7	-	-	35.5	85.6	9.3	-	18.4	ND (<0.0005)	0.004	0.004	0.015	0.108	ND (<0.0008)	
興村排水	112/1/11	-	23.4	7.8	-	-	45.3	126	13.4	-	16.7	ND (<0.0005)	ND (<0.0030)	0.006	0.025	0.064	0.002	
廬山橋	112/2/8	5.0	26.0	7.8	826	5.9	11.8	33.1	12.9		17.1							
台林橋																		水深不足，無採樣
華興橋	112/2/9	5.0	22.3	7.6	1340	5.1	11.5	30.0	10.9		10.1							
忠義橋	112/2/8	1.0	22.5	8.0	724	8.0	2.8	7.3	4.5		0.25							
永欽一號橋	112/2/8	5.8	22.5	7.4	867	3.8	12.3	24.7	8.6		8.50							
蘭潭進水口																		水深不足，無採樣
蘭潭取水口	112/2/8	1.0	22.0	8.6	477	8.3	1.3	3.8	3.7		0.12							
香湖公園	112/2/8	6.8	25.6	7.5	646	4.2	20.8	58.9	12.4		9.98							
頂庄社區(入)	112/2/8	6.8	24.8	7.7	826	2.3	18.0	41.5	6.0		13.0							
頂庄社區(出)	112/2/8	5.8	21.9	7.7	700	2.5	12.9	24.7	9.7		12.1							
十四甲排水	112/2/8	8.0	23.9	7.5	2010	3.6	31.3	113	60.2		13.0							
民雄排水	112/2/8	3.3	26.6	7.6	3790	5.7	6.2	25.1	11.1		0.51							
北區排水	112/2/8	6.0	24.1	7.7	844	4.7	24.5	53.7	15.4		14.2							
西區排水	112/2/9	6.0	24.2	7.9	829	6.4	25.9	60.7	9.8		14.1							
中央排水	112/2/9	6.0	23.9	8.2	894	4.6	43.1	87.1	12.3		18.2							
南排排水	112/2/8	7.8	21.8	7.6	764	1.6	31.3	63.1	7.9		16.5							
興村排水	112/2/8	6.8	21.1	7.5	917	3.9	56.5	115	14.8		30.3							
廬山橋	112/3/8	3.3	22.0	7.4	685	5.4	14.4	32.0	11.0		0.75							
台林橋	112/3/8	4.5	23.4	7.7	883	6.6	30.7	43.0	18.1		2.83							
華興橋	112/3/8	5.8	22.1	7.6	1510	4.4	14.6	57.4	17.6		4.77							
忠義橋	112/3/8	1.0	23.4	8.2	572	7.5	2.5	19.6	5.9		0.30							
永欽一號橋	112/3/8	3.3	25.7	7.7	826	6.2	14.2	33.3	11.0		0.87							
蘭潭進水口																		水深不足，無採樣
蘭潭取水口	112/3/8	1.0	24.5	8.5	388	7.5	1.8	13.4	4.8		0.16							
香湖公園	112/3/8	6.8	20.8	7.5	340	4.1	17.6	44.3	7.3		4.83							
頂庄社區(入)	112/3/8	4.0	22.6	7.5	633	5.8	10.9	37.5	3.6		2.59							
頂庄社區(出)	112/3/8	6.3	22.7	7.7	604	3.6	15.3	51.2	22.8		2.51							
十四甲排水	112/3/8	6.5	21.4	8.1	724	6.0	30.1	154	20.5		7.35							
民雄排水	112/3/8	2.8	25.5	7.7	417	6.0	12.5	60.1	15.0		0.38							
北區排水	112/3/8	6.0	23.0	7.8	883	6.2	26.5	64.9	15.5		6.46							
西區排水	112/3/8	6.8	20.9	7.7	699	2.9	24.6	70.4	11.8		5.80							
中央排水	112/3/8	6.8	21.9	7.5	567	4.3	21.3	73.2	9.6		4.17							
南排排水	112/3/8	6.8	24.2	7.8	703	3.0	40.3	80.1	13.7		5.65							
興村排水	112/3/8	8.0	25.7	7.4	908	4.0	52.9	180	63.2		7.89							